

# **PROBLEM SUMMARY**

Sample Rating Trend

WATER



# KAESER 8371836

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

#### COMPONENT CONDITION SUMMARY



#### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Water	%	ASTM D6304	>0.05	<u> </u>				
ppm Water	ppm	ASTM D6304	>500	<u>▲</u> 5110				
Debris	scalar	*Visual	NONE	▲ MODER				
Appearance	scalar	*Visual	NORML	▲ HAZY				
Free Water	scalar	*Visual		<b>1.0</b>				

Customer Id: RAMSANFL Sample No.: KC104191 Lab Number: 05646635 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.			



# **OIL ANALYSIS REPORT**

Sample Rating Trend



**WATER** 



# **KAESER 8371836**

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

#### **DIAGNOSIS**

#### Recommendation

Oil and filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We recommend an early resample in 500 hours to monitor this condition.

#### Wear

All component wear rates are normal.

#### Contamination

Appearance is hazy. Free water present. There is a moderate concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil.


#### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Sep2022		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KC104191		
Sample Date				12 Sep 2022		
Machine Age	hrs			5548		
Oil Age	hrs			3030		
Oil Changed				Changed		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	<1		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>3	0		
Titanium	ppm	ASTM D5185m	>3	0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>10	<1		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>50	4		
Tin		ASTM D5185m	>10	<1		
	ppm		>10	0		
Vanadium Cadmium	ppm	ASTM D5185m ASTM D5185m		0		
	ppm		11 21 /1			
ADDITIVES		method	limit/base		history 1	history 2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m	90	<1		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	90	51		
Calcium	ppm	ASTM D5185m	2	2		
Phosphorus	ppm	ASTM D5185m		5		
Zinc	ppm	ASTM D5185m		10		
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	2		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	4		
Water	%	ASTM D6304	>0.05	<b>△</b> 0.511		
ppm Water	ppm	ASTM D6304	>500	<u>▲</u> 5110		
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.37		
VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	▲ MODER		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	▲ HAZY		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.05	0.2%		
Free Water	scalar	*Visual		1.0	Service Manag	er - RAMSANF





### **OIL ANALYSIS REPORT**




**GRAPHS** 

# Ferrous Alloys









Certificate L2367

Laboratory Sample No. Lab Number

: KC104191 : 05646635 Unique Number : 10141174 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 20 Sep 2022 : 22 Sep 2022 Diagnostician : Jonathan Hester **RAM STEEL FRAMING** 1150 ALBRIGHT RD SANFORD, FL USA 32771

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F:

history 2

history 2

no image

no image