



# SAMPLE SUBMISSION FORM

## Oil Analysis Laboratories

501 Madison Avenue Cary, NC 27513 USA 1-800-237-1369 (919) 379-4102 Fax (919) 379-4050	C8-1175 Appleby Line Burlington, ON L7L 5H9 CANADA 1-800-268-2131 (905) 569-8600 Fax (905) 569-8605
---	--

WEARCHECK sample kits will be replaced with unused kits if defective in manufacture, labeling, or packaging, or if lost by us or any associate company even though by negligence or other fault.

WEARCHECK shall not be liable or responsible for the future performance or failure of any engine, piece of equipment or material involved in any test or sample. The Company makes no warranties, representations, or guaranties with respect to the performance of any such engine, piece of equipment, or material.

**NOTE 1:** For sample identification, please ensure that you either print labels and place on the sample bottle or that you label the sample cap with the reference number (\*Label) shown below.

**NOTE 2:** Please attach 33 Sample Information Forms (SIFs) as proof of payment for these analysis.

### Shipping Info







Shipped Via: null  
 Tracking Number:  
 Shipped On: 09/01/2023  
 Submitted By: Daniel Ingaramo [HOLCIM (ARGENTINA) S.A.]

### SAMPLING INSTRUCTIONS AND PRECAUTIONS

For best results we suggest the following precautions when taking the sample.

**INSTRUCTIONS FOR TAKING SAMPLE** - the SAMPLE should not be taken MORE THAN 30 MINUTES after shutdown, and the oil should have been in service for at least 10 hours or 500 miles, before the oil can accurately reflect wear conditions. **AVOID CONTAMINATION OF THE SAMPLE** - Clean around the drain plug before draining. Remove the drain, and when about half the oil has run out, catch the sample by inserting the bottle into the oil stream. The bottle should be at least 3/4 filled. Do not remove the bottle cap until you are ready to take the sample, and recap the bottle immediately after filling. Take care not to confuse samples from different units. Or, remove sample with a suction pump by inserting the siphon tube down the dipstick tube or into the sump/reservoir. The siphon tube must be clean by either replacement or rinsing with a solvent and drying. Do not rinse with gasoline or diesel fuel. Or, Engines with sample ports (i.e. gauge plugs, probalizer mini-plugs), follow the specific instructions pertaining to the sampling device purchased.

### HOLCIM (ARGENTINA) S.A. / CAPDEVILLE - MENDOZA

	*Label : 388957	Machine Id	431-GU1	Machine Age :
	Sample Number : LL10000106	Component	Gear Reducer	Fluid Age :
	Test Package : PLANT	Fluid		Filter Age :
	Sample Date : 08/25/2023			Fluid Maintenance :
				Filter Maintenance :
<hr/>				
	*Label : 388949	Area	HORNO	Machine Age :
	Sample Number : LL10000105	Machine Id	461-AK1	Fluid Age :
	Test Package : PLANT	Component	AUXILIAR	Filter Age :
	Sample Date : 08/25/2023	Fluid		Fluid Maintenance :
				Filter Maintenance :
<hr/>				
	*Label : 388966	Area	HORNO	Machine Age :
	Sample Number : LL10000104	Machine Id	461-EL2	Fluid Age :
	Test Package : PLANT	Component	Hydraulic System	Filter Age :
	Sample Date : 08/25/2023	Fluid		Fluid Maintenance :
				Filter Maintenance :
<hr/>				
	*Label : 388969	Area	HORNO	Machine Age :
	Sample Number : LL10000103	Machine Id	461-EL3	Fluid Age :
	Test Package : PLANT	Component	CORONA HORNO	Filter Age :
	Sample Date : 08/25/2023	Fluid		Fluid Maintenance :
				Filter Maintenance :
<hr/>				
	*Label : 381397	Area	HORNO	Machine Age :
	Sample Number : LL10000024	Machine Id	471-TZ1-M1	Fluid Age :
	Test Package : MOB 1	Component	1 Gear Reducer	Filter Age :
	Sample Date : 02/08/2023	Fluid	(--- GAL)	Fluid Maintenance : Changed
				Filter Maintenance :
<hr/>				
	*Label : 381399	Area	HORNO	Machine Age :
	Sample Number : LL10000023	Machine Id	471-TZ1-M1	Fluid Age :
	Test Package : MOB 1	Component	1 Gear Reducer	Filter Age :
	Sample Date : 08/02/2023	Fluid	(--- GAL)	Fluid Maintenance : Changed
				Filter Maintenance :



\*Label : 381410  
 Sample Number : LL10000027  
 Test Package : MOB 1  
 Sample Date : 02/08/2023

Area : HORNO  
 Machine Id : 471-TZ1-M3  
 Component : 1 Gear Reducer  
 Fluid : (--- LTR)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 381745  
 Sample Number : LL10000028  
 Test Package : MOB 1  
 Sample Date : 02/08/2023

Area : HORNO  
 Machine Id : 471-TZ1-M3  
 Component : 1 Gear Reducer  
 Fluid : (--- LTR)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 381746  
 Sample Number : LL10000026  
 Test Package : MOB 1  
 Sample Date : 08/02/2023

Area : HORNO  
 Machine Id : 471-TZ1-M4  
 Component : 1 Gear Reducer  
 Fluid : (--- LTR)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 381747  
 Sample Number : LL10000025  
 Test Package : MOB 1  
 Sample Date : 02/08/2023

Area : HORNO  
 Machine Id : 471-TZ1-M4  
 Component : 1 Gear Reducer  
 Fluid : (--- LTR)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 381402  
 Sample Number : LL10000029  
 Test Package : MOB 1  
 Sample Date : 02/08/2023

Area : HORNO  
 Machine Id : 471-TZ1.M2  
 Component : 1 Gear Reducer  
 Fluid : (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 381409  
 Sample Number : LL10000030  
 Test Package : MOB 1  
 Sample Date : 02/08/2023

Area : HORNO  
 Machine Id : 471-TZ1.M2  
 Component : 1 Gear Reducer  
 Fluid : (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 386285  
 Sample Number : LL10000108  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area : HORNO  
 Machine Id : 471-UH1  
 Component : Not Applicable  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 378173  
 Sample Number : LL10000122  
 Test Package : PLANT  
 Sample Date : 07/21/2023

Area : HORNO  
 Machine Id : 471-VE8  
 Component : Gear Reducer  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 388954  
 Sample Number : LL10000101  
 Test Package : PLANT  
 Sample Date : 08/25/2023

Area : HORNO  
 Machine Id : 471-VE8  
 Component : Gear Reducer  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 388975  
 Sample Number : LL10000100  
 Test Package : PLANT  
 Sample Date : 08/25/2023

Area : HORNO  
 Machine Id : 491-RP1  
 Component : Gear Reducer  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 388951  
 Sample Number : LL10000099  
 Test Package : PLANT  
 Sample Date : 08/25/2023

Area : HORNO  
 Machine Id : 491-TK1  
 Component : Gear Reducer  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 382781  
 Sample Number : LL10000121  
 Test Package : MOB 1  
 Sample Date : 07/08/2023

Area : HORNO  
 Machine Id : CA.431-CN1  
 Component : ATLAS COPCO Air Compressor  
 Fluid : (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance : Changed  
 Filter Maintenance :



\*Label : 381861  
 Sample Number : LL10000033  
 Test Package : MOB 1  
 Sample Date : 03/08/2023

Machine Id CA.K91-EC1  
 Component Gear Reducer  
 Fluid (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 381862  
 Sample Number : LL10000031  
 Test Package : MOB 1  
 Sample Date : 03/08/2023

Machine Id CA.L83-BC1  
 Component Gear Reducer  
 Fluid (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 388960  
 Sample Number : LL10000102  
 Test Package : PLANT  
 Sample Date : 08/25/2023

Area HORNO  
 Machine Id CA421-EL1  
 Component Gear Reducer  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 388973  
 Sample Number : LL10000107  
 Test Package : PLANT  
 Sample Date : 08/25/2023

Area HORNO  
 Machine Id CA421-VE2  
 Component Gear Reducer  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386280  
 Sample Number : LL10000118  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH1  
 Component Northeast Bearing  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386288  
 Sample Number : LL10000119  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH1  
 Component SUR OESTE  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386290  
 Sample Number : LL10000117  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH1  
 Component NOROESTE  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386293  
 Sample Number : LL10000115  
 Test Package : MOB 1  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH2  
 Component PISTA 2  
 Fluid (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386294  
 Sample Number : LL10000114  
 Test Package : MOB 1  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH2  
 Component Northeast Bearing  
 Fluid (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386295  
 Sample Number : LL10000116  
 Test Package : MOB 1  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH2  
 Component Southeast Bearing  
 Fluid (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386296  
 Sample Number : LL10000113  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH2  
 Component PISTA 2  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386297  
 Sample Number : LL10000110  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area HORNO  
 Machine Id CA461-RH3  
 Component PISTA 3  
 Fluid

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386299  
 Sample Number : LL10000111  
 Test Package : PLANT  
 Sample Date : 08/17/2023

Area : HORNO  
 Machine Id : CA461-RH3  
 Component : PISTA 3  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 386302  
 Sample Number : LL10000112  
 Test Package : MOB 1  
 Sample Date : 08/17/2023

Area : HORNO  
 Machine Id : CA461-RH3  
 Component : Northeast Bearing  
 Fluid : (--- GAL)

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :



\*Label : 381858  
 Sample Number : LL10000032  
 Test Package : PLANT  
 Sample Date : 03/08/2023

Machine Id : L83-MX1  
 Component : MIXER DE BARROS  
 Fluid :

Machine Age :  
 Fluid Age :  
 Filter Age :  
 Fluid Maintenance :  
 Filter Maintenance :